



5-WAY Ntrate, Nitrite, pH, Alkalinity and Total Hardness

25 Test Strips

Code 3038-G

Immerse strip. SWIRL 2 TIMES.

Remove with pads face up.

DO NOT SHAKE OFF EXCESS

WATER. Immediately read

Hardness > Alkalinity.

Wait 30 seconds, read **pH > Nitrite > Nitrate.**

- Keep wet fingers out of the vial
- For best results read in natural light
- Close vial tightly after removing strip
- Store in a cool, dry place

LaMotte Company
Chesertown, Maryland 21620 USA
www.lamotte.com

NO₃ Nitrate ppm	Fresh & Salt									
	0	20	40	OK	OK	OK	OK	OK	OK	OK
NO₂ Nitrite ppm	Fresh & Salt									
	0	0.5	1	OK	OK	OK	OK	OK	OK	OK
pH	Fresh									
	6.0	6.5	7.0	OK	OK	OK	OK	OK	OK	OK
	Salt									
	6.0	6.5	7.0	OK	OK	OK	OK	OK	OK	OK
Alk Alkalinity ppm	Fresh & Salt									
	0	40	80	OK	OK	OK	OK	OK	OK	OK
TH Hardness ppm	Fresh									
	0	30	60	OK	OK	OK	OK	OK	OK	OK



8

46306

37396

6

Drop holding box and dotted tolerance line